


**Punto id intervento**



A photograph showing the interior of a severely damaged room. A large, arched opening in the wall leads to another area. The walls are crumbling, and there is a significant amount of debris on the floor. A window with a grid pattern is visible on the right side of the frame.

A photograph showing the interior of a damaged building, likely a school, with debris on the floor and a doorway leading to another room. The walls are light-colored and show signs of wear and damage. The floor is covered in rubble and debris. A doorway in the background leads to another room, which appears to be a classroom with a chalkboard and a door. The overall scene suggests a state of significant disrepair and destruction.

A photograph of a tunnel under construction. The left wall is made of rough concrete with several large pipes and conduits running along it. The right wall is made of brick. The floor is covered in debris, including bricks, wood, and other construction materials. The tunnel appears to be in an early stage of development.

A photograph of a large, rectangular, underground structure, likely a bunker or shelter, with a tiled floor and walls. The structure is built into a hillside, and the interior is dimly lit. The walls are made of concrete or stone, and the floor is covered in tiles. There are some wooden planks and debris scattered on the floor.